

NIQ

Dated: 28.2. 2013

Fabric Surface Friction Tester based on Low Stress Measurement.

Essential requirements are:

1. Sensor Based Measurement
2. Low Stress Measurement suitable for apparel fabric
3. Must be compatible with KES-FB system to evaluate fabric hand

(Dr. B.K. Behera)